

Instructions:

1. Ensure that all pages are printed.
2. Use Black ball pen only
3. Change in option is not allowed
4. There is no negative marking
5. Use of non-programmable scientific calculator is allowed

1. Equation which relates pressure, volume and temperature of a gas is called the
A Equation of state
B Gibb's-Duhem equation
C Ideal gas equation
D Maxwell's equation
2. Eutectoid product in Fe-C system is called
A Pearlite
B Bainite
C Ledeburite
D Spheroidite
3. Which one of the following is not a strong bond?
A Van der Waals bond
B Covalent bond
C Metallic bond
D Ionic bond
4. Fatigue is phenomena caused by
A stress above ultimate tensile stress
B Cyclic stress
C Both a and b
D None of these
5. In fcc lattice, the packing sequence of atoms is
A AB AB AB.....
B BC BC BC.....
C AC AC AC.....
D ABC ABC.....
6. Diffusion can occur in _____ materials.
A Solid
B Liquid
C Gaseous
D All
7. The line/surface in an equilibrium diagram which indicates the temperature of the beginning of solidification or completion of melting is called
A Solidus
B Liquidus
C Solidification
D Melting
8. Plastic deformation results from the following
A Slip
B Twinning
C Both
D None

9. What is the emissivity of a black body?
 A 1 B 0
 C 0.9 D 0.5
10. To predict out of any two metal which should corrode on coupling _____ can be used.
 A EMF Series B Periodic Table
 C Weight of Metal D Area of Metal
11. Failure due to excessive deformation is controlled by _____.
 A Material properties B Design & Dimensions
 C Both (a) and (b) D None
12. Extractive metallurgy is the combination of
 A Process metallurgy and physical metallurgy Chemical metallurgy and physical metallurgy
 C Process metallurgy and chemical metallurgy Process metallurgy and material science
13. Usual casting method for making dental crowns
 A Sand casting B Die casting
 C Continuous casting D Investment casting
14. Suitable case hardening process for plain carbon steel, containing 0.2 per cent carbon is
 A Carburizing B Nitriding
 C Cyaniding C Carbo-nitriding
15. In bcc crystals the direction of close packed plane is
 A $\langle 100 \rangle$ B $\langle 010 \rangle$
 C $\langle 111 \rangle$ D $\langle 001 \rangle$
16. In Ellingham diagram, lower position oxide is more ----- oxide than upper position oxide
 A Unstable B Strong
 C Stable D Weak
17. T T T diagram is also known as
 A S-curve or C-curve B Bain's curve
 C Isothermal transformation diagram D All A, B and C
18. Frank-Read source is concerned with
 A Dislocation B Diffusion
 C Age hardening D None of these
19. Corrosion of metals involves
 A Physical reactions B Chemical reactions
 C Both D None
20. Duralumin is an alloy of aluminium,
 A Copper and manganese B Nickel and silicon
 C and nickel D None of these
21. Free carbon distributed throughout the mass in ductile cast iron is in the form of
 A Nodules B Flakes
 C Needles D Crystals
22. In connection with the corrosion of metals, passivation is the process that
 A Intensifies deterioration B Changes the composition of the metal
 C Inhibits further deterioration D None of these
23. Recrystallization temperature depends on
 A Amount of prior cold work B Carbon content
 C Purity of alloy D Both (A) and (B)
24. Strain-time curve is plotted of

- A Tensile Test B Fatigue test
C Creep test D Hardness test
25. Which of the following steel making processes does not employ oxygen blowing in the converter?
A Acid Bessemer converter B Kaldor rotary converter
C L.D. converter D Basic open-hearth furnace
26. With respect to the matrix of Al-Cu alloys, G-P zones are
A Coherent B Incoherent
C Semi-coherent D Chemically indistinguishable
27. The stress below which failure never occurs in fatigue even for an indefinitely large number of loading cycles is known as
A Yielding limit B Endurance limit
C Stress corner D Proof stress
28. The equilibrium constant for any reaction is explained by
A Sievert’s law B Hess’s law
C Law of mass action D Henry’s law
29. The word ‘ceramic’ meant for
A Soft material B Hard material
C Burnt material D Dry material
30. In normalizing, one of the following is not correct
A It relieves internal stresses B It produces a uniform structure
C The rate of cooling is rapid D The rate of cooling is slow
31. The metal is subjected to mechanical working for
A Refining grain size B Reducing original block into desired shape
C Controlling the direction of flow lines D All of these
32. Oxygen to acetylene ratio in case of oxidizing flame is
A 1:1 B 1.5:1
C 2:1 D 2.5:1
33. Excess of lime addition in basic steel making processes makes
A The slag viscous B The slag fluid
C No change in slag viscosity D Hot heat
34. Martensite is formed by _____ transformation.
A Diffusion B Isothermal
C Athermal D None of these
35. Prandtl number is the ratio of
A Mass diffusivity to thermal diffusivity B Momentum diffusivity to thermal diffusivity
C Thermal diffusivity to mass diffusivity D Thermal diffusivity to momentum diffusivity

36. The technology called metal injection molding (MIM) involves the use of
A Standard metal powders B Sub-sieve metal powders
C Oxidized metal powders D Heavily lubricated metal powders
37. The adhesiveness is the property of sand due to which
A It evolves a great amount of steam and other gases B The sand grains stick together
C It clings to the sides of a moulding box D None of these
38. The hardness of quenched Martensite
A increases with increasing carbon percentage B decreases as carbon percentage increases
C first increases and then remains almost constant as the carbon percentage increases D first increases and then decreases as carbon percentage increases
39. Cup-shaped articles like bath tubs are generally made from flat sheets by ----- operation.
A Rolling B Forging
C Extrusion D Deep-drawing
40. During LD blow in steelmaking the impurity that gets removed first is
A Carbon B Phosphorous
C Manganese D Silicon
41. Steel is
A An alloy of iron and carbon B Pure iron
C Oxidized iron D A mixture of iron and silver
42. Miller indices of the diagonal plane of a cube are
A (200) B (111)
C (010) D (110)
43. Super saturated solid solution of carbon in alpha iron is known as
A Austenite B Cementite
C Ferrite D Martensite
44. Cold worked components are generally subjected to
A Normalizing B Tempering
C Annealing D Shot peening
45. In a single-component condensed system, if degree of freedom is zero, maximum number of phases that can co-exist

- | | | | |
|---|---|---|---|
| A | 0 | B | 1 |
| C | 2 | D | 3 |
46. Aluminium alloys find use in aircraft industry because of
- | | | | |
|---|---------------------------|---|------------------|
| A | High strength | B | Low sp. Gravity |
| C | Good corrosion resistance | D | Good weldability |
47. Sulphide ore is generally concentrated by
- | | | | |
|---|---------------------|---|--------------------------|
| A | Roasting | B | Froth floatation process |
| C | Reduction by carbon | D | Tempering |
48. In salt bath furnaces, heat is transferred to the charge mainly by
- | | | | |
|---|------------|---|---------------|
| A | Conduction | B | Convection |
| C | Radiation | D | None of these |
49. The following phenomena are useful in zone-refining process
- | | | | |
|---|--------|---|-------------|
| A | Coring | B | Segregation |
| C | Both | D | None |
50. In secondary stage of Creep, creep rate is
- | | | | |
|---|----------|---|---------------|
| A | Minimum | B | Maximum |
| C | Constant | D | Unpredictable |
51. Alpha brasses have composition
- | | | | |
|---|-----------------|---|-----------------|
| A | 60 % Cu-40 % Zn | B | 70 % Cu-30 % Zn |
| C | 80 % Cu-20 % Zn | D | 75 % Cu-25 % Zn |
52. The entropy -----, when a spontaneous change occurs in an isolated system.
- | | | | |
|---|--------------|---|------------------|
| A | Decreases | B | Increases |
| C | Is unchanged | D | Is equal to zero |
53. The teeth of spur gear are hardened by
- | | | | |
|---|----------------------|---|---------------------|
| A | Cold working | B | Quenching |
| C | Dispersion hardening | D | Induction hardening |
54. Which is the ore of lead?
- | | | | |
|---|--------|---|-----------|
| A | Galena | B | Anglesite |
|---|--------|---|-----------|

- | | | |
|--|-------------|---------------|
| | C Cerussite | D Cassiterite |
|--|-------------|---------------|
55. What is the most common carbon steel found in boilers, pressure vessels, tanks, and piping?
- | | |
|---------------------|-----------------------|
| A Low carbon steel | B Medium carbon steel |
| C High carbon steel | D None of these |
56. Turbine blade failure occurs due to
- | | |
|----------------|-----------------|
| A Creep | B Fatigue |
| C A and B both | D None of these |
57. The coke bed height in cupola is height of the coke from
- | | |
|----------------------|-----------------------|
| A Slag tapping spout | B Metal tapping spout |
| C Tuyeres level | D Charging platform |
58. Shatter index of B.F. coke is a measure of its
- | | |
|--------------|-------------------|
| A Strength | B Hardness |
| C both A & B | D neither A nor B |
59. The purpose of a riser is to
- | | |
|---------------------------------------------------------------------------------|-------------------------------------------------------|
| A Deliver molten metal into the mould cavity | B Act as a reservoir for the molten metal |
| C Feed the molten metal to the casting in order to compensate for the shrinkage | D Deliver the molten metal from pouring basin to gate |
60. Rolling machine is amenable to NC CNC is
- | | |
|----------------------------------|-----------------------------------|
| A Pyramid machine | B Three roll single pinch machine |
| C Four roll double pinch machine | D Three roll double pinch machine |
61. The material in which there is conduction primarily by holes is
- | | |
|------------------------|------------------------|
| A Conductor | B Insulator |
| C p-type semiconductor | D n-type semiconductor |
62. Leaching of roasted zinc ore is done by
- | | |
|--------------------|--------------------------|
| A Dilute H_2SO_4 | B Concentrated H_2SO_4 |
| C Dilute HCl | D Dilute HNO_3 |
63. Seamless tube can be produced by
- | | |
|--------------------------|----------------------------------------------|
| A Two high rolling mills | B Ring rolling combined with stretch forming |
| C Piercing | D Steam hammer forging |
64. Ball mill is used for
- | | |
|-----------------|-------------------|
| A Crushing | B Coarse grinding |
| C Fine grinding | D Attrition |
65. A minute surface or sub-surface crack present in a brass specimen may be tested by
- | | |
|--------------------------|----------------------------|
| A Visual inspection | B Magnetic particle method |
| C Dye-penetration method | D none of these |
66. Cast Iron failure is of _____ type.
- | | |
|----------------|-----------------|
| A Cup and cone | B Top to Bottom |
| C Knife | D Brittle |

67. A tooth paste tube can be produced by
 A Solid forward extrusion B Solid backward extrusion
 C Hollow backward extrusion D Hollow forward extrusion
68. Number of component (C), phase (P) and degrees of freedom (F) are related by Gibb's phase rule as
 A $P+F-C=2$ B $C=P-F+2$
 C $F=C-P-2$ D $P=F-C-2$
69. Sweep pattern is used for moulding parts having
 A Rectangular shape B Elliptical shape
 C Circular shape D Complicated shape having intricate details'
70. Which substance is used to decrease the melting point of alumina in Hall - Haroult process?
 A CuSO_4 B Cryolite
 C Gypsum D Limonite
71. In four stand high mills the backup rolls are_____ work rolls.
 A Smaller than B Bigger than
 C Equal to D None of these
72. Which of the following is a line defect found in metal crystals?
 A Grain boundaries B Cracks
 C Edge dislocations D None of these
73. Iron is non-magnetic
 A Above Curie point B When its lattice structure is fcc
 C When it is in γ -iron form D All A, B and C
74. Which of the following alloying elements, when added to plain C steel, increase its corrosion / oxidation resistance?
 A Chromium B Cobalt
 C Molybdenum D Tungsten
75. For high temperature creep application, the desirable grain size is
 A Fine B Coarse
 C Ultra-fine D None of these
76. For selecting material for spring which of following properties are considered.
 A Stiffness B Fatigue

77. The property which enables metals to be drawn into wire is known as
 C A and B both D Creep
 A Malleability B Ductility
 C Straining D Elastic deformation
78. Damage to metal surface caused by mechanical action is called
 A Pitting B Corrosion
 C Erosion D None of these
79. Metal matrix composite is made of
 A Metal matrix with metal reinforcement B Metal matrix with ceramic reinforcement
 C Metal matrix with polymer reinforcement D None of above
80. In L-D steelmaking, the final slag can be best described as
 A Oxidizing B Basic
 C Oxidizing and basic D Reducing and basic
81. The lowest eigen value of the matrix $\begin{bmatrix} 4 & 2 \\ 1 & 3 \end{bmatrix}$ is
 A 1 B 2
 C -1 D 5
82. The system of linear equations $x + 2y = 5$; $4x + 8y = 12$; $3x + 6y + 3z = 15$ has
 A No solution B Unique solution
 C Infinitely many solutions D None
83. If $z = \sin\left(\frac{x-y}{x+y}\right)$ then the value of $x \frac{\partial z}{\partial x} + y \frac{\partial z}{\partial y}$ is
 A $2 \sin\left(\frac{x-y}{x+y}\right)$ B 1
 C 0 D $\sin\left(\frac{x-y}{x+y}\right)$
84. The function $f(x, y) = 2x^2 + 2xy - y^3$ has
 A Only one stationary point at (0,0) B stationary points : (0,0) $\left(-\frac{1}{6}, \frac{1}{3}\right)$
 C stationary points at: (0,0)(-1,1) D stationary points : (0,0) $\left(\frac{1}{6}, -\frac{1}{3}\right)$
85. $\lim_{a \rightarrow b} \frac{a^b - b^a}{a^a - b^b} =$
 A $\frac{1 + \log b}{1 - \log b}$ B 0
 C $\frac{1 - \log b}{1 + \log b}$ D e
86. The area bounded by the parabola $y = x^2$ and the lines $x = 4$ and $y = 0$ is equal to

- A 64
C 128/3
- B 64/3
D none

87. Changing the order of integration of $I = \int_0^2 \int_{x^2}^{2x} f(x,y) dy dx$ leads to the integral $I = \int_r^s \int_p^q f(x,y) dy dx$ the value of q is

- A 0
C \sqrt{y}
- B $y/2$
D 4

88. If $y(x) = x + \sqrt{x + \sqrt{x + \sqrt{x + \dots \infty}}}$ then $y(4) =$

- A $\frac{9+\sqrt{17}}{2}$ or $\frac{9-\sqrt{17}}{2}$
C $\frac{9+\sqrt{17}}{2}$ only
- B $\frac{9-\sqrt{17}}{2}$ only
D ∞

89. The directional derivative of $u(x,y,z) = x^2 + 2y^2 + z$ at a point $(1, 1, 2)$ in the direction of $3i - 4j$ is

- A -4
C -1
- B -2
D 1

90. The curl of the gradient of the scalar field $v(x,y,z) = 2xyx^2 + 3xy^2z + 4xyz^2$ is

- A 0
C $4xyi + 6yzj + 8xzk$
- B 1
D $4xy + 6yz + 8xz$

91. Consider a company that assembles computers. The probability of a faulty assembly of any computer is p . The company subjects each computer to a testing process. This testing process gives the correct result for any computer with a probability q . What is the probability of a computer being declared faulty ?

- A $pq + (1-p)(1-q)$
C $(1-p)q$
- B $(1-q)p$
D pq

92. The solution of $\frac{d^2y}{dx^2} - 25y = e^{3x}$ is

- A $y = C_1 \cos 5x + C_2 \sin 5x + e^{3x}/16$
C $y = C_1 e^{5x} + C_2 e^{-5x} + e^{3x}/16$
- B $y = C_1 e^{5x} + C_2 e^{-5x} - e^{3x}/16$
D $y = C_1 \cos 5x + C_2 \sin 5x - e^{3x}/16$

93. If $f(z) = u(x,y) + iv(x,y)$ is an analytic function of complex variable z then

- A $u_x = v_y, u_y = v_x$
C $u_x = -v_y, u_y = v_x$
- B $u_x = -v_y, u_y = -v_x$
D $u_x = v_y, u_y = -v_x$

94. The solution of $yy' + 25x = 0$ represents

- A Family of circles
C Family of parabolas
- B Family of ellipses
D Family of hyperbolas

95. The number of boundary condition required to solve the partial differential equation

$$\frac{\partial^2 u}{\partial x^2} + \frac{\partial^2 u}{\partial y^2} = 0$$

- A 1
C 4
- B 2
D none

96. The inverse Laplace transforms of $\frac{1}{s(s+1)}$ is
- | | | | |
|---|----------|---|-----------------|
| A | $\sin t$ | B | $e^{-t} \sin t$ |
| C | e^{-t} | D | $1 - e^{-t}$ |
97. If $f(z) = x^3 - 3xy^2 + iv(x, y)$ is an analytic function then $v(x, y)$
- | | | | |
|---|---------------------------------|---|---------------------------------|
| A | $y^3 - 3x^2y + \text{constant}$ | B | $3x^2y - y^3 + \text{constant}$ |
| C | $x^4 - 4x^3y + \text{constant}$ | D | $xy - y^2 + \text{constant}$ |
98. If C is the simple closed curve around the origin then the value of $\oint_C \frac{\sin z}{z} dz$
- | | | | |
|---|----------|---|------------|
| A | 0 | B | $2\pi i$ |
| C | ∞ | D | $1/2\pi i$ |
99. The iteration formula to find the n^{th} root of a positive real number b by using the Newton-Raphson method is
- | | | | |
|---|---------------------------------------------------------|---|---------------------------------------------------------|
| A | $x_{k+1} = \frac{(n-1)x_k^n + \sqrt[n]{b}}{nx_k^{n-1}}$ | B | $x_{k+1} = \frac{(n-1)x_k^n - \sqrt[n]{b}}{nx_k^{n-1}}$ |
| C | $x_{k+1} = \frac{(n-1)x_k^n + b}{nx_k^{n-1}}$ | D | $x_{k+1} = \frac{(n-1)x_k^n - b}{nx_k^{n-1}}$ |
100. Trapezoidal's rule for integration gives exact result when $f(x)$ is a polynomial function of degree less or equal to
- | | | | |
|---|---|---|---|
| A | 1 | B | 2 |
| C | 3 | D | 4 |